

NAVIGATIONAL WARNING 111/22

TOBAGO

CHART BA 477

NW 107/22 refers

Masters and operators of all marine craft are hereby advised that the following beacons have been restored to normal:

1. Smith Island beacon FLW 5s 5NM position:

Lat. 11-11.80 N
Long 060-39.06 W

2. Courland Point beacon LFLW 10s 8NM position:

Lat. 11-13.32 N
Long 060-46.80 W

3. Crown Point beacon FL (4)W 20s 12NM position:

Lat. 11-08.88 N
Long 060-50.68 W

Caution is advised.

DATUM WGS 84

29th November 2022

Signed
Ronald Alfred
Director of Maritime Services
Maritime Services Division
Ministry of Works and Transport