

NAVIGATIONAL WARNING 106/22

TRINIDAD – SOUTH COAST

CHART BA 481

NW 013/22 and 043/19 rescinded

Masters and operators of all marine craft are hereby advised that the following beacons:

1. Taparo Point beacon FL (3) W 15s 14NM position:

Lat. 10 – 03.53 N

Long 061 – 37.55 W

2. Punta Del Arena beacon FL W 7.5s 16NM position:

Lat. 10 – 02.97 N

Long 061 – 55.67 W

has been restored to normal.

Caution is advised.

DATUM WGS 84

8th November 2022

Signed
Ronald Alfred
Director of Maritime Services
Maritime Services Division
Ministry of Works and Transport