

NOTICE TO MARINERS 01/24
NAVIGATIONAL WARNING 041/24
TRINIDAD GULF OF PARIA & TOBAGO

Chart BA 1044 & 1045

NW 003/22 , 033/24 , 054/19, 013/23 , 100/19, 032/22 and 041/22 are rescinded

Masters and operators of all marine craft are hereby advised that the following Navigational Aids:

TRINIDAD GULF OF PARIA

Middle Channel beacon **FL G 3s** is missing from position:

Lat 10 - 03.95 N
Long 061 - 58.68 W

Three Fathom bank beacon **FL R 3s** is missing from position:

Lat 10-03.70 N
Long 061- 57.43 W

Oropouche Bank beacon **VQ W** is unlit at position:

Lat 10 – 17.07 N
Long 061 – 33.85 W

TRINIDAD NORTH COAST

Tetron Rock beacon **FL G 5s** is missing from position:

Lat 10 – 40.97 N
Long 061 – 40.10 W

Diamond Rock beacon **VQ (9) W 10s]** is missing from position:

Lat 10 - 40.25 N
Long 061 -46.35 W

Darien Rock beacon **FL(2) W 10s** is missing from position:

Lat 10 – 31.97 N
Long 060 – 37.48 W

TOBAGO

Buccoo Reef North buoy beacon **QW** is missing from position:

Lat 11 – 11.87 N
Long 060 – 50.01 W

Buccoo Reef West buoy beacon **VQ(9)W 10s** is missing from position:

Lat 11 -11.12 N
Long 060 - 51.10 W

Great River Shoal beacon **VQ(6)+LFLW10s** is missing from position:

Lat 11 – 10.80 N
Long 060 – 37.39 W

Minster Rock beacon **Q(6)+LFLW 15** is missing from position:

Lat 11 - 09.82 N
Long 060 - 42.17 W

Bulldog Shoal beacon **VQ(6)LFW 10s** is missing from position:

Lat 11– 08.92 N
Long 060 – 44.55 W

Extreme caution is advised.

DATUM WGS 84

1st March 2024

Signed
Ronald Alfred
Director Maritime Services
Maritime Services Division
Ministry of Works and Transport