

NAVIGATIONAL WARNING 064/24

TOBAGO SOUTHWEST COAST

CHART BA 477

Masters and operators of all marine craft are hereby advised that a **South Cardinal Buoy** light characteristic **VQ (6) LFW 10s 4NM** was installed at position:

Lat 11 -07.90 N

Long 060- 47.14 W

Extreme caution is advised.

DATUM WGS 84

26th March 2024

Signed
Ronald Alfred
Director of Maritime Services
Maritime Services Division
Ministry of Works and Transport