

NAVIGATIONAL WARNING 210/24

TRINIDAD – SOUTH COAST

CHART BA 481

185/24 is rescinded

Masters and operators of all marine craft are hereby advised that **Victor Carter Buoy
FL VQ (9) W 15s 4NM** has been restored to normal at position:

Lat. 10 – 08.62 N
Long 061 – 51.38 W

Caution is advised.

DATUM WGS 84

28th October 2024

Signed
Ronald Alfred
Director of Maritime Services
Maritime Services Division
Ministry of Works and Transport