

NAVIGATIONAL WARNING 033/24

TRINIDAD SOUTH WEST COAST

CHART BA 1045

Masters and operators of all marine craft are hereby advised that **Three Fathom Bank Buoy** a red cylindrical shape buoy, light characteristic **FL R 3s** is **Lit** and **missing** from its station at position:

Lat 10-03.70 N

Long 061- 57.43 W

Any sighting or **Salvage Operation** of the buoy is to be reported to the Trinidad and Tobago Coast Guard or the Maritime Services Division.

Extreme caution is advised.

DATUM WGS 84

6th February 2024

Signed

Ronald Alfred
Director of Maritime Services
Maritime Services Division
Ministry of Works and Transport