

**NOTICE TO MARINERS 02/24**

**NAVIGATIONAL WARNING 055/24**

**TRINIDAD SOUTH EAST COAST**

**CHART BA 501**

Masters and operators of all marine craft are hereby advised that **Yellow Rectangular Shape buoy** light characteristic **FL 5 Y 20s 5 NM** was installed at position:

**Lat 09-56.79 N**

**Long 060- 15.55 W**

Extreme caution is advised.

**DATUM WGS 84**

14<sup>th</sup> March 2024

Signed  
Ronald Alfred  
Director of Maritime Services  
Maritime Services Division  
Ministry of Works and Transport