

NAVIGATIONAL WARNING 011/22

TRINIDAD - EAST COAST

CHART BA1044

Masters of vessels are hereby notified that the **BRIGAND HILL LIGHTHOUSE FL(2 + 1) W30s** has been restored to normal at position:

Lat 10 – 29.61 N

Long 061 – 04.20 W

Caution is advised.

DATUM WGS 84

15th February 2022

Signed
Ronald Alfred
Director of Maritime Services
Maritime Services Division
Ministry of Works and Transport