

# **NAVIGATIONAL WARNING 106/19**

## **TRINIDAD – NORTH EAST COAST**

### **CHART BA 1045**

**NW091/19 refers**

Masters of vessels are hereby notified that the **Geotechnical and Geophysical** survey currently in progress by vessel **HAVILA SUBSEA** with the use of a remotely operated vehicle (ROV) along with barge **TRINITY VII DANIELLA** at five offshore Blocks **will continue from 18<sup>th</sup> December 2019 to 31<sup>st</sup> January 2020** at the following positions:

### **EAST MAYARO BLOCK**

- |   |   |   |
|---|---|---|
| 1. Lat 10 - 05.99 N<br>Long 060 - 18.51 W | 2. Lat 10 - 06.71 N<br>Long 060 - 17.92 W | 3. Lat 10 - 06.16 N<br>Long 060 - 17.42 W |
| 4. Lat 10 - 05.81 N<br>Long 060 - 17.42 W | 5. Lat 10 - 05.16 N<br>Long 060 - 17.38 W | 6. Lat 10 - 01.80 N<br>Long 060 - 19.98 W |
| 7. Lat 10 - 01.21 N<br>Long 060 - 20.71 W | 8. Lat 10 - 05.68 N<br>Long 060 - 18.13 W |   |

### **SOUTH EAST GALEOTA BLOCK**

- |   |   |   |
|---|---|---|
| 1. Lat 09 - 55.69 N<br>Long 069 - 25.20 W | 2. Lat 09 - 55.75 N<br>Long 060 - 27.48 W | 3. Lat 09 - 54.88 N<br>Long 060 - 31.91 W |
| 4. Lat 09 - 55.19 N<br>Long 060 - 31.79 W | 5. Lat 09 - 56.04 N<br>Long 060 - 27.54 W | 6. Lat 09 - 56.15 N<br>Long 060 - 25.61 W |
| 7. Lat 09 - 56.72 N<br>Long 060 - 25.17 W | 8. Lat 09 - 56.65 N<br>Long 060 - 25.08 W |   |

### **TEAK SAMAN POUI BLOCK**

- |   |   |   |
|---|---|---|
| 1. Lat 10 - 00.31 N<br>Long 060 - 48.56 W | 2. Lat 10 - 04.40 N<br>Long 060 - 59.62 W | 3. Lat 10 - 04.75 N<br>Long 060 - 58.71 W |
| 4. Lat 10 - 04.52 N<br>Long 060 - 58.12 W | 5. Lat 10 - 04.24 N<br>Long 060 - 57.78 W | 6. Lat 10 - 00.49 N<br>Long 060 - 47.76 W |

**MAYARO/ GUAYAGUARE BAY BLOCK**

- |   |   |   |
|---|---|---|
| 1. Lat 10 - 07.79 N<br>Long 061 - 00.11 W | 2. Lat 10 - 07.98 N<br>Long 060 - 59.85 W | 3. Lat 10 - 08.27 N<br>Long 060 - 59.88 W |
| 4. Lat 10 - 08.30N<br>Long 060 - 59.73W   | 5. Lat 10 - 08.20 N<br>Long 060 - 59.63 W | 6. Lat 10 - 08.01 N<br>Long 060 - 59.51 W |

**SINGLE POINT MOORING S-11 BLOCK**

- |   |   |
|---|---|
| 1. Lat 10 - 06.24 N<br>Long 060 - 59.22 W | 2. Lat 10 - 05.49 N<br>Long 060 - 58.83 W |
|---|---|

A wide berth and extreme caution is advised.

**DATUM WGS 84**

10<sup>th</sup> December 2019

Signed  
Ronald Alfred  
Director of Maritime Services  
Maritime Services Division  
Ministry of Works and Transport